

OKD 058078775

RECEIVED
EPA REGION VI
1986 JUN 25 PM 3:19
SUPERFUND BRANCH

MEMORANDUM

DATE: June 25, 1986

SUBJECT: Potential Hazardous Waste Site - Site Inspection Report

FROM: Oscar Cabra, Jr., P.E. *Oscar Cabra*
Chief, Water Supply Branch (6W-S)

TO: Martha McKee
Chief, Superfund Compliance Section (6H-ES)

In response to the CERCLA investigation reports which you recently sent to the Water Supply Branch, I am attaching our comments. Thank you for the opportunity to review these documents.

Attachments

1. Sun Refining and Marketing Co. - Tulsa OK

OKD058078775

cc: Carl Hickam (6H-ES)

SUPERFUND FILE

AUG 27 1992

REORGANIZED

REVIEW

Potential Hazardous Waste Site - Inspection Report

DKD058078775

Site Name San Refining and Marketing Co.

Site Location Tulsa, OK

Site Number OK 1911 Date of Survey Dec. 20, '86

Inspected by _____ State FIT ☒ TAT _____

Other (specify) _____

Received From M. Muka

Date rec'd by Water Supply Branch 6/16/86

Type samples:

<input checked="" type="checkbox"/> on-site	<input type="checkbox"/> on-site	<input type="checkbox"/> on-site	<input type="checkbox"/> on-site
<input type="checkbox"/> SOIL	<input type="checkbox"/> SURFACE WATER	<input type="checkbox"/> GROUND WATER	<input type="checkbox"/> DRINKING WATER
<input checked="" type="checkbox"/> off-site	<input type="checkbox"/> off-site	<input checked="" type="checkbox"/> off-site	<input type="checkbox"/> off-site

Type contaminant(s):

☒ ORGANICS ☒ INORGANICS ☐ RADIONUCLIDES ☐ MICROBIOLOGICAL

Summary:

Report states that there is probably no surface contamination of the Arkansas River. The lagoons may contribute to contamination of the shallow ground water. This flows northward to the Arkansas River. The area is heavily industrialized along this section of the River. No water supplies take water from the Arkansas River prior to Webber Falls Reservoir.

RECOMMENDATION: No recommendation for sampling.

Concurrence:

D. R. Linn 6/23/86

Edward A. Jeffery 6/19/86
Signature and Date